
PHF FX51-150X200



d (in) 5.91 D (mm) 200 d _w (mm) - L (mm) - L ₁ (mm) 34 L ₂ (mm) 40 L ₃ (mm) 54 B (mm) 68 D ₁ (mm) - e (mm) - F _t Transmissible axial force (kN) 333 Mt Transmissible torque (Nm) 25000 P _w Shaft surface pressure (N/mm²) 175 P _n Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut - M _s Screw 230	Bushing no.	FX51
D (mm) 200 d _w (mm) - L (mm) - L ₁ (mm) 34 L ₂ (mm) 40 L ₃ (mm) 54 B (mm) 68 D ₁ (mm) - e (mm) - F _t Transmissible axial force (kN) 333 axial force (kN) M _t Transmissible torque (Nm) 25000 P _w Shaft surface pressure (N/mm²) 175 P _n Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	d (mm)	150
dw (mm) - L (mm) - L1 (mm) 34 L2 (mm) 40 L3 (mm) 54 B (mm) 68 D1 (mm) - e (mm) - Ft Transmissible axial force (kN) 333 Mt Transmissible torque (Nm) 25000 Pw Shaft surface pressure (N/mm²) 175 Pn Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws nut -	d (in)	5.91
L (mm) - L1 (mm) 34 L2 (mm) 40 L3 (mm) 54 B (mm) 68 D1 (mm) - d1 (mm) - e (mm) - Ft Transmissible axial force (kN) 333 Mt Transmissible torque (Nm) 25000 Pw Shaft surface pressure (N/mm²) 175 Pn Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	D (mm)	200
L1 (mm) 34 L2 (mm) 40 L3 (mm) 54 B (mm) 68 D1 (mm) - e (mm) - f Transmissible axial force (kN) 333 Mt Transmissible torque (Nm) 25000 Pw Shaft surface pressure (N/mm²) 175 Pn Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws nut -	d _w (mm)	-
L2 (mm) 40 L3 (mm) 54 B (mm) 68 D1 (mm) 209 d1 (mm) - e (mm) - Ft Transmissible axial force (kN) 333 axial force (kN) Mt Transmissible torque (Nm) 25000 Pw Shaft surface pressure (N/mm²) 175 Pn Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	L (mm)	-
L3 (mm) 54 B (mm) 68 D1 (mm) 209 d1 (mm) - e (mm) - Ft Transmissible axial force (kN) 333 Mt Transmissible torque (Nm) 25000 Pw Shaft surface pressure (N/mm²) 175 Pn Hub surface pressure (N/mm²) 130 Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	L ₁ (mm)	34
B (mm) 68 D ₁ (mm) 209 d ₁ (mm) - e (mm) - F _t Transmissible 333 axial force (kN) M _t Transmissible torque (Nm) P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	L ₂ (mm)	40
D ₁ (mm) D ₁ (mm) d ₁ (mm) e (mm) F _t Transmissible axial force (kN) M _t Transmissible torque (Nm) P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty Clamp screws nut 209 209 130 131 135 130 130 130 130 130	L ₃ (mm)	54
d ₁ (mm) - e (mm) - F _t Transmissible 333 axial force (kN) M _t Transmissible 25000 torque (Nm) P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	B (mm)	68
e (mm) - F _t Transmissible 333 axial force (kN) M _t Transmissible 25000 torque (Nm) P _w Shaft surface 175 pressure (N/mm²) P _n Hub surface 130 pressure (N/mm²) Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	D ₁ (mm)	209
F _t Transmissible axial force (kN) M _t Transmissible torque (Nm) P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty Clamp screws size M14 Clamp screws nut 333 25000 175 175 180 180 190 190 100 100 100 100	d ₁ (mm)	-
axial force (kN) M _t Transmissible torque (Nm) P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty Clamp screws size M14 Clamp screws nut	e (mm)	-
M _t Transmissible torque (Nm) P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty Clamp screws size Clamp screws nut M14	F _t Transmissible	333
torque (Nm) P _w Shaft surface 175 pressure (N/mm²) P _n Hub surface 130 pressure (N/mm²) Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	<u> </u>	
P _w Shaft surface pressure (N/mm²) P _n Hub surface pressure (N/mm²) Clamp screws Qty Clamp screws size M14 Clamp screws nut		25000
pressure (N/mm²) P _n Hub surface 130 pressure (N/mm²) Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -		175
P _n Hub surface 130 pressure (N/mm²) Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -		1/3
pressure (N/mm²) Clamp screws Qty Clamp screws size M14 Clamp screws nut -	·	130
Clamp screws Qty 10 Clamp screws size M14 Clamp screws nut -	11	150
Clamp screws size M14 Clamp screws nut -		10
Clamp screws nut -		M14
		-
1115 001 011	M _s Screw	230

® SKF is a registered trademark of the SKF Group
© SKF Group 2012
The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.



tightening torque	
(Nm)	
Weight (kg)	5.7

® SKF is a registered trademark of the SKF Group
© SKF Group 2012
The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

